





JPVAP03





v013
24.05.2021
A. P.
[cm]





BENITO











A.

B.

C.



44x M10x120 (SD)


4x M8x120 (SD)




NOT INCLUDED



NOT INCLUDED



E37




[cm]










7h






ST/INOX		PLYWOOD / HDPE	
	E37 (SD)	2x	E8 (S1)
2x	E34 (SB, SD)	2x	E152 (S6)
2x	E88 (SD)	2x	PS1
6x	E1	1x	PS26
2x	E3	1 x	E4
2x	E42	1x	PS91
1x	E51	1x	PS31
1x	E28	1x	PS55
1x	E89	3x	CE1
1x	E239	2x	CE4
		2x	CE31
		2x	CE3
		2x	CE111









2x **E42**



2x **E3**




022100
12x




022102
2x

022102
4x

021102
2x






4x **E1**



2x **PLYWOOD PS1**

[cm]








025144
1x

022106 (SB)
022120 (SD)
1x

1x **E239**



2x **CE1**




021152
2x


021152
2x

021179
1x


021110
2x




1x **E88**



1x **E4**




1x **CE1**





1x **CE4**

[cm]









PLYWOOD
PS31
1x



1x E51






1x E28



PLYWOOD
PS26
1x




[cm]









[cm]





[cm]






1x HDPE
CE31




x2



011143 011119



2x

2x






1x

HDPE
CE3



1x

HDPE
CE111



[cm]

